

Time	Site	Component	Substrate	Side	Condition		Floor	Room		Depth Ind P	bC	PbC Error
8/18/2005 10:46	2724	WINDOW FRAME	WOOD	WEST	CRACKED	BLUE	FIRST	OUTSIDE	Negative	1	0	0.02
8/18/2005 10:47	2724	EXT. WALL	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	10	5.1	1.1
8/18/2005 10:49	2724	FLOOR	CONCRETE	WEST	PEELING	GREY	FIRST	PORCH	Negative	1	0.01	0.02
8/18/2005 10:51	2724	EXT. WALL	BRICK	NORTH	CRACKED	GREY	FIRST	OUTSIDE	Negative	1.65	0.06	0.03
8/18/2005 10:52	2724	EXT. WALL	WOOD	SOUTH	CRACKED	WHITE	FIRST	OUTSIDE	Positive	3.29	1.4	0.3
8/18/2005 10:53	2724	TRIM	WOOD	EAST	CRACKED	BLUE	FIRST	OUTSIDE	Positive	2.93	1.9	0.3
8/18/2005 10:54	2724	EXT. WALL	WOOD	SOUTH	CRACKED	WHITE	FIRST	SHED	Negative	1.78	0.01	0.02
				<u> </u>								
												
· · · · · · · · · · · · · · · · · · ·					<u> </u>							
											-	
	 						i		 			
			-						 			
Note: Readings	are in mo	/cm²	 									
				<u> </u>	 	<u> </u>						
Dainted surface	e not test	ed were assessed t	o he in "intoc	t" conditi	on at time of	site vicit			 			

Property ID # 2724 / 3742 High Street



West exposure of property; house has new paint throughout